

Case Study

Asbestos Removal

Project Name: Queens Road, Esher.

Project Duration: 2 Weeks

Project Brief

SCK Group Ltd were contracted to carry out emergency works to a fire damaged block of apartments at short notice we enabled our site teams to carry out removal of asbestos containing materials on site to allow extensive temporary works to the structure of the building, the overall project lasted 14 days in which time SCK fully decontaminated the boiler house along with a full de-plant of all plant and equipment within the boiler house, textured coating removal to the apartments and communal landing along with removal of Asbestos Insulating Board to internal and external areas under fully controlled conditions.

Due to SCK's fast response time, collaborative working and on site methods of work the client was able to retain a majority possession of the building which was a great cost saving to the client for the refurbishment of the block of apartments.



CASE STUDY

Head Office

SCK Group Ltd, First Floor, West Wing,
The Quad'angle, Crewe Hall,
Weston Road, Crewe, CW1 6UY
Tel: 01270 667 013
Email: enquiries@sckgroup.co.uk

Southern Office

SCK Group Ltd, Dartford Business Park
Victoria Road, Dartford, Kent DA1 5FS
Email: enquiries@sckgroup.co.uk

Home Counties Office

SCK Group Ltd, Endeavour House,
Wrest Park, Silsoe, Bedfordshire, MK45 4HS
Email: enquiries@sckgroup.co.uk