



## Case Study

### Asbestos Removal

**Project Name:** School - Kent

**Project Scope:** Safe removal of thermal insulation residues to walls and sectional pipework on school premises.

#### Project Brief

SCK Group was commissioned to undertake the safe removal of asbestos containing materials within a basement boiler-house at a Kent school during seasonal closure.

Works were planned and notified appropriately and in accordance with the control of Asbestos Regulations and supporting legislation.

Air monitoring, including backgrounds, leak testing and personal monitoring was carried out throughout the project before a full 4 stage clearance and certificate of re-occupation.

The licensed asbestos work was audited by the internal compliance team and the site team were commended for their level of positive engagement and work ethic.

The site was well arranged and housekeeping was noted as exceptional.



Y  
U  
D  
T  
U  
S  
T  
U  
D  
Y  
C  
A  
S  
E  
S  
T  
U  
D  
Y

#### Head Office

**SCK Group Ltd,** Endeavour House,  
Wrest Park, Silsoe, Bedfordshire, MK45 4HS  
Email: [enquiries@sckgroup.co.uk](mailto:enquiries@sckgroup.co.uk)

#### Southern Office

**SCK Group Ltd,** Dartford Business Park  
Victoria Road, Dartford, Kent DA1 5FS  
Email: [enquiries@sckgroup.co.uk](mailto:enquiries@sckgroup.co.uk)

#### North West Office

**SCK Group Ltd,** First Floor, West Wing,  
The Quadrangle, Crewe Hall,  
Weston Road, Crewe, CW1 6UY  
Tel: 01270 667 013  
Email: [enquiries@sckgroup.co.uk](mailto:enquiries@sckgroup.co.uk)