



Case Study

Asbestos Removal

Project Name: Leroy House, 436 Essex Road, London, N1
Project Value: £116,000.00
Project Duration: 4 Weeks

Project Brief

Based in Islington, SCK Group previously conducted the safe removal, disposal and encapsulation of over 100 high level asbestos cement collars and removal of the sprinkler system sections to facilitate these works. Our site teams also carried out removal of textured coatings containing asbestos to concrete rendered walls via needle guns within respirator zones within multiple floors of offices, studios and workshops.

Our Demolition division carried out the removal of all windows and window frames to the building to make way for the planned refurbishment of the building.

Both SCK Group and SCK Demolition showed their ability to carry our works in conjunction together to deliver a seamless project ahead of the planned completion date and gave the client an opportunity to gain critical time on their programme due to the efficiency and execution of our work on this project.



CASE STUDY